

STAIR WITH ADJACENT RAMP AND CONTINUOUS HANDRAILS

TGSI WARNING INDICATORS



STAIR WITH ADJACENT RAMP AND CONTINUOUS HANDRAILS

TGSI WARNING INDICATORS

DTAC 0006
LAYOUT DIAGRAM
TACTILE GROUND SURFACE INDICATORS (TGSI)-WARNING
VERSION 03
PUBLISHED 28.10.11

DTAC[®]

DTAC 0006 LAYOUT DIAGRAM

DETAILS

Installation Notes:
TGSI Warning Indicators installed on a stair with adjacent ramp and continuous handrails

PROJECT

Mulgrave Country Club

This project required a standard application of Warning TGSI's to the top and bottom of the paths of travel between two levels of this entry. Two TGSI areas of 600mm by the width in between the path of travel (in this case in between the handrails) were employed to give a clear tactile cue for both the approach and the alighting from the stair and ramp. For further detail and information see AS/NZS 1428.4 (2002).

INSTALLATION

TGSI's (Warning)

NOTES

Layout of discrete warning TGSI's
Drawings in millimetres
Drawings not to scale unless noted

LEGEND

- Area requiring TGSI installation
- Installed handrail
- ← Upward gradient along path of travel

DISCLAIMER

No one should act or rely upon the information contained within this document without first referring to the current AS/NZS 1428.1 (2009)—Design for Access and Mobility (Part 1: General Requirements for Access—New Building Work) and the current AS/NZS 1428.4.1 (2009)—Means to Assist the Orientation of People with Vision Impairment (Tactile Ground Surface Indicators), satisfying themselves that any proposed installations are in accordance with such standards or other applicable building regulations, including the National Construction Code (NCC) (effective from 01.05.11)—previously referred to as the Building Code of Australia (BCA)—and in particular the 'deemed-to-satisfy-provisions' of the NCC and Disability (Access to Premises—Buildings) standards, as they apply from one situation to another. Furthermore, the information provided is solely for the purposes of TGSI's and is not related to the design, configuration or formation to stairs, handrails, ramps, accessible paths and 'way-finding' depicted therein.

© DTAC Pty Ltd
ABN 41 093 070 127, May 2011
Reproduction is by written permission only and must accompany the brand and copyright acknowledgement of DTAC Pty Ltd.

DTAC PTY LTD

PO BOX 5059
SOUTH MELBOURNE VIC 3205
AUSTRALIA
T 1300 793 478
F 1300 780 628
SOLUTIONS@DTAC.COM.AU
WWW.DTAC.COM.AU

FIGURE 0006-A




FIGURE 0006-B

